

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- Name of the School : Smbana Vilukamanda mission school
1. Name of the Officer : Lakshmi P.N (A-E)
2. Location : Thamburam Nagar road  
Namsam
3. Period for which the certificate is issued : 2023-24
4. Types of building : R.C.C.
5. Nature of defect if any :  
a) Foundation and basement :  
b) Superstructure :  
d) Wood work wrought and put up :  
e) Roof :  
f) Flooring :  
g) Miscellaneous (Cracks if any) :  
ix 27.25x6.25x4.00  
multi storied building  
Nil
6. Any Major defects notices which will render the building unsafe in any manner : NO
7. Whether maintenance works have been done properly : yes
8. Whether the structure is sound or not for conducting classes : The building is safe under normal wind and weather conditions

**Note:-**

1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

## CERTIFICATE

Certified that the School was inspected by me on .....5/05/2023.....  
and found to be fit / unfit to conduct classes for the period .....2023-24.....  
for the reason stated above.

Place: .....Namsam.....

Date: .....5/05/23.....



08/05/23 DE  
Assistant Engineer  
Thamburam Nagar  
Namsam